

8-HOUR NORM/TENORM RADIATION SAFETY OFFICER REFRESHER (DECONTAMINATION FOCUS) COURSE OUTLINE

- Section 1.0 DECONTAMINATION PLANNING**
 - 1.1 Project Planning
 - 1.2 Job Site Notifications & Open Record Requests
 - 1.3 Corporate Radiation Safety Officer (RSO)
 - 1.4 Field Radiation Safety Officer (RSO)
 - 1.5 Crewmembers - Workers
 - 1.6 Evaluations
 - 1.7 Standard On-Site Records

- Section 2.0 ON-SITE DECONTAMINATION**
 - 2.1 Mobilization and Site Setup
 - 2.2 Protective Equipment Worn by the Worker
 - 2.3 Radiation Work Permits (RWP)
 - 2.4 TLD Badges
 - 2.5 Background Radiation Surveys
 - 2.6 Restricted Areas
 - 2.7 Air Sample Collection
 - 2.8 Sampling Waste
 - 2.9 Surveys
 - 2.10 Equipment Marking/Labeling
 - 2.11 Contamination On A Person
 - 2.12 Job Closeout
 - 2.13 Internal CRSO Audits

- Section 3.0 DATA INTERPRETATION**
 - 3.1 Data Analysis
 - 3.2 Restricted Area Boundary
 - 3.3 Air Monitoring
 - 3.4 Air Sample Results and Analysis
ALI and DAC Tables (Texas)
 - 3.5 Bioassay
 - 3.6 Dosimetry Analysis
 - 3.7 Site Inventory of Radioactive Material

- Section 4.0 RECYCLING, RECLAMATION & DISPOSAL**
 - 4.1 Scrap Metal Recycling
 - 4.2 Oil Reclamation
 - 4.3 Waste Characterization
 - 4.4 Waste Profiling
 - 4.5 Common Waste Conversions
 - 4.6 Commercial Disposal Facilities
 - 4.7 Certificate of Disposal

- Section 5.0 RECORDS MANAGEMENT**
 - 5.1 Records Summary
 - 5.2 Job Files





NORM SOLUTIONS LLC
200 S. Crowley Road, Box 233
Crowley, TX 76036-0233
(844) 315-3061 Ofc

8-HOUR NORM/TENORM RADIATION SAFETY OFFICER REFRESHER (DECONTAMINATION FOCUS) COURSE OUTLINE

- 5.3 Personnel Files
- 5.4 Notifications and Reports to Occupational Workers
- 5.5 Calibration Records
- 5.6 Inventory Records
- 5.7 Releases for Unrestricted Use Documentation
- 5.8 Inspections
- 5.9 Example Forms

WRITTEN EXAM

